

RESCUE HELICOPTER HOIST AREA INSPECTION

# CERTIFICATE

## B2 OSS

### OWF BALTIC 2

The rescue helicopter hoist area on stated offshore substation and located in mentioned offshore wind farm has been inspected according to national legal regulations (SOLF) and, where applicable, to other national standards for offshore installations. The rescue hoist area has been found suitable for helicopter hoist operations subject to below stated limitations, non-compliances and authorization by the approving authority.

#### RESCUE HELICOPTER HOIST AREA INFORMATION

| HEIGHT RHHA | POSITION                    | MAX. LOAD CAPACITY   |
|-------------|-----------------------------|----------------------|
| 87 ft MSL   | N 54° 58.33'. E 013° 09.69' | 5.0kN/m <sup>2</sup> |

#### LIMITATIONS

NIL

#### NON-COMPLIANCES


FOR NON-COMPLIANCES SEE HELICOPTER RESCUE HOIST AREA MANUAL

#### NEXT DUE

11.01.2026

22.11.2024

Inspection date



Inspected by