

### RESCUE HELICOPTER HOIST AREA INSPECTION

# **CERTIFICATE**

## **AL OSS**

### **OWF ALBATROS**

The rescue helicopter hoist area on stated offshore substation and located in mentioned offshore wind farm has been inspected according to national legal regulations (SOLF) and, where applicable, to other national standards for offshore installations. The rescue hoist area has been found suitable for helicopter hoist operations subject to below stated limitations, non-compliances and authorization by the approving authority.

#### RESCUE HELICOPTER HOIST AREA INFORMATION

HEIGHT RHHA	POSITION	MAX. LOAD CAPACITY
116 ft MSL	N 54° 29.22′. E 006° 16.23′	1.120 kg
/ \		
	LIMITATIONS	
3/:	NIL	
	NON-COMPLIANCES	
FOR NON-COMPLIANCES SEE HELICOPTER RESCUE HOIST AREA MANUAL		
NEXT DUE		
12.11.2024		
26.11.2023  Inspection date	CERTIFIED  Seffen Bechtel	1. $\bigcap$ $\bigcap$ Inspected by
Inspection date	CFA77FIC ATO T	Inspected by