

## HELIDECK INSPECTION

# CERTIFICATE

## AMRUMBANK (EDYA)

### AMRUM-OFFSHORE WEST GMBH

The above-mentioned helideck has been inspected according to legal national and international requirements (SOLF, AVV-HFP, EASA 965/2012, ICAO Annex 14 Vol. II and ICAO Heliport Manual) and, where applicable, to other national standards for offshore helidecks (CAP 437).

The helideck has been found suitable for helicopter operations subject to below stated limitations, non-compliances and authorization by the approving authority. For more details see respective *Helideck Information Chart*.

## HELIDECK INFORMATION

D VALUE	POSITION	MTOW
23 m	N 54° 31' 11.69'' E 007° 44' 05.61''	12.8 t

## LIMITATIONS

TEMPORARILY VFR DAY ONLY

## NON-COMPLIANCES


NIL

## NEXT DUE

25.08.2023

25.08.2022

Inspection date

Inspected by