

HELIDECK INSPECTION

CERTIFICATE

AMRUMBANK (EDYA)

AMRUM-OFFSHORE WEST GMBH

The above-mentioned helideck has been inspected according to legal national and international requirements (AVV-HFP, EASA 965/2012, ICAO Annex 14 Vol. II and ICAO Heliport Manual) and, where applicable, to other national standards for offshore helidecks (CAP 437). The helideck has been found suitable for helicopter operations subject to below stated limitations, non-compliances and authorization by the approving authority. For more details see respective *Helideck Information Chart*.

HELIDECK INFORMATION

D VALUE	POSITION	MTOW
23 m	N 54° 31′ 11.69" E 007° 44′ 05.61"	12.8 t
	LIMITATIONS	
	TEMPORARILY VFR DAY ONLY	
	NON-COMPLIANCES	
	NIL	
	775-100/	
	· SPECIS	
	NEXT DUE	
	31.12.2022	
	Steffen Bechtel	
11.05.2021		101
Inspection date	BDSF-geprüfter Sachverständiger für Offshore Flugbetrieb, Hubschrauberlandedecks und Windenbetriebsflächen	Inspected by
mspection date	BDSF \$20020 MARKET	inspected by
	SOTSCHER SACHVERSTÄNDIGER UND	