

### HELIDECK INSPECTION

# **CERTIFICATE**

## WK OSS (EDYW)

### IBERDROLA RENOVABLES DEUTSCHLAND GMBH

The above-mentioned helideck has been inspected according to legal national and international requirements (AVV-HFP, EASA 965/2012, ICAO Annex 14 Vol. II and ICAO Heliport Manual) and, where applicable, to other national standards for offshore helidecks (CAP 437). The helideck has been found suitable for helicopter operations subject to below stated limitations, non-compliances and authorization by the approving authority. For more details see respective *Helideck Information Chart*.

#### HELIDECK INFORMATION

D VALUE	POSITION	MTOW
23.50 m	N 54° 50.06′ E 014° 04.46′	13.0 t
	A POLICE	
	LIMITATIONS	
	LIMITATIONS	
/ 2	TEMPORARILY VFR DAY ONLY	5
	NON COMPLIANCES	
NON-COMPLIANCES		
	• NIL	•
NEXT DUE		
NEXT DOE		
	31.12.2020	
	Steffen Bechte/	o 1
	Sterren bechref	
17.12.2019	*	
Inspection date	BDSF-geprüfter Sachverständiger für Offshore Flugbetrieb, Hubschrauberlandedecks und Windenbetriebsflächen	Inspected by
	BDSF 8260120 100 100 100 100 100 100 100 100 100	
	DEUTSCHER SACHVERSTÄNDIGER UND PRO-	