

### HELIDECK INSPECTION

# **CERTIFICATE**

## WK OSS (EDYW)

### IBERDROLA RENOVABLES DEUTSCHLAND GMBH

The above-mentioned helideck has been inspected according to legal national and international requirements (AVV-HFP, EASA 965/2012, ICAO Annex 14 Vol. II and ICAO Heliport Manual) and, where applicable, to other national standards for offshore helidecks (CAP 437). The helideck has been found suitable for helicopter operations subject to below stated limitations, non-compliances and authorization by the approving authority. For more details see respective *Helideck Information Chart*.

### **HELIDECK INFORMATION**

D VALUE	POSITION	MTOW
23.50 m	N 54° 50.06′ E 014° 04.46′	13.0 t
	10	
	LIMITATIONS	
/	LIMITATIONS	
/ 2	TEMPORARILY VFR DAY ONLY	
	/· · · · · · ·	T \
	NON-COMPLIANCES	
	NIL	
	\· .:/	
	1	
	NEXT DUE	
	SHELL	
	31.12.2021	
	Steffen Bechtel	$\wedge$ 1
	R 3 9	
20.10.2020	BDSF-geprüfter Sachverständiger für Offshore Flugbetrieb, Hubschrauberlandedecks	, , –
Inspection date	und Windenbetriebsflächen	Inspected by
	BDSF \$16012 UND TANK	

SCHER SACHVERSTÄNDIGER UND