

HELIDECK INSPECTION

CERTIFICATE

DBUOSS (EHGM)

NORTHLAND DEUTSCHE BUCHT GMBH

The above-mentioned helideck has been inspected according to legal national and international requirements (SOLF, AVV-HFP, EASA 965/2012, ICAO Annex 14 Vol. II and ICAO Heliport Manual) and, where applicable, to other national standards for offshore helidecks.

The helideck has been found suitable for helicopter operations subject to below stated limitations, non-compliances and authorization by the approving authority. For more details see respective *Helideck Information Chart*.

HELIDECK INFORMATION

| D VALUE | POSITION | MTOW |
|--|--|--------------|
| 22.20 m | N 54° 18.17' E 005° 47.20' | 13 t |
| | | \ |
| /. < | LIMITATIONS | |
| | Environo | |
| | NIL | |
| | | |
| | !!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!! | |
| | NON-COMPLIANCES | |
| | NIL | |
| FOR FURTHER DETAILS SEE AERODROME INSTRUCTIONS | | |
| | | |
| | | |
| 175012 | | |
| NEXT DUE | | |
| 30.05.2025 | | |
| | 30.03,2023 | |
| | | |
| | IN SOMEC | |
| 26.04.2024 | CERTIFIED CONTROL OF THE PROPERTY OF THE PROPE | 1.01 |
| | Cert-Nr: 1-14-1012 Steffen Bechtel | • |
| Inspection date | CEPTIFIC MICO | Inspected by |