

HELIDECK INSPECTION

# CERTIFICATE

MO-OSS (EDYO)

MERKUR OFFSHORE GMBH

The above-mentioned helideck has been inspected according to legal national and international requirements (AVV-HFP, EASA 965/2012, ICAO Annex 14 Vol. II and ICAO Heliport Manual) and, where applicable, to other national standards for offshore helidecks (CAP 437). The helideck has been found suitable for helicopter operations subject to below stated limitations, non-compliances and authorization by the approving authority. For more details see respective *Helideck Information Chart*.

## HELIDECK INFORMATION

D VALUE	POSITION	MTOW
22.20 m	N 54° 02,24' E 006° 33,65'	13 t

### LIMITATIONS

TEMPORARILY VFR DAY ONLY

### NON-COMPLIANCES

NIL

FOR FURTHER DETAILS SEE AERODROME INSTRUCTIONS

### NEXT DUE

31.12.2020

11.09.2019

Inspection date



Inspected by