

#### HELIDECK INSPECTION

# **CERTIFICATE**

# NORDSEE ONE (EDYN)

## Nordsee One GmbH

The above-mentioned helideck has been inspected according to legal national and international requirements (AVV-HFP, EASA 965/2012, ICAO Annex 14 Vol. II and ICAO Heliport Manual) and, where applicable, to other national standards for offshore helidecks (CAP 437). The helideck has been found suitable for helicopter operations subject to below stated limitations, non-compliances and authorization by the approving authority. For more details see respective *Helideck Information Chart*.

### HELIDECK INFORMATION

D VALUE	POSITION		MTOW
20.90 m	N 53° 58.94'	E 006° 50.17°	12.8 t
	8		
/:-	LIMITA	TIONS	
/ <	TEMPORARILY V	FR DAY ONLY	2
HELICOPTE	R OPERATIONS WITH L	ANDING NET INSTAL	LLED ONLY
	NON-COMP	PLIANCES	•
	NII	L ./	
FOR FU	RTHER DETAILS SEE A	ERODROME INSTRUC	CTIONS
	75 NEXT	DUE	
	31.12.2	2021	

10.06.2020

Inspection date



Inspected by

Inspected by