

HELIDECK INSPECTION

CERTIFICATE

SEAFOX 7

SEAFOX

The above-mentioned helideck has been inspected according to legal national and international requirements (AVV-HFP, EASA 965/2012, ICAO Annex 14 Vol. II and ICAO Heliport Manual) and, where applicable, to other national standards for offshore helidecks (CAP 437). The helideck has been found suitable for helicopter operations subject to below stated limitations, non-compliances and authorization by the approving authority. For more details see respective *Helideck Information Chart*.

HELIDECK INFORMATION

D VALUE	POSITION	MTOW
19.50 m	VARIABLE	9.3 t

LIMITATIONS

NIL

NON-COMPLIANCES

OBSTACLE-FREE SECTOR INFRINGED BY PORTSIDE LEG

NEXT DUE

04.09.2021

05.09.2020

Inspection date



Hartmann

Inspected by