

HELIDECK INSPECTION

CERTIFICATE

SEAFOX2

SEAFOX

The above-mentioned helideck has been inspected according to legal national and international requirements (AVV-HFP, EASA 965/2012, ICAO Annex 14 Vol. II and ICAO Heliport Manual) and, where applicable, to other national standards for offshore helidecks (CAP 437). The helideck has been found suitable for helicopter operations subject to below stated limitations, non-compliances and authorization by the approving authority. For more details see respective *Helideck Information Chart*.

HELIDECK INFORMATION

D VALUE	POSITION	MTOW
22.20 m	VARIABLE (9.5 t
LIMITATIONS		
NO HELICOPTER LANDINGS WHILE AFLOAT		
NON-COMPLIANCES		
OBSTACLE-FREE SECTOR INFRINGED BY HANDRAILS		
7500cte		
NEXT DUE		
	30.06.2020	
	Jan-Henrik Barkow	
11.06.2019 Inspection date	BDSF-Geprüfter Sachverständiger für Offshore Flugbetrieb, Hubschrauberlandedecks & Windenbetriebsflächen	Inspected by
AND DEUTSCHER SACHVERSTÄNDIGER UND TALEBE		
	ONER SACHVERSTÄNDIGER	