

HELIDECK INSPECTION

CERTIFICATE

SEAFOX2

SEAFOX

The above-mentioned helideck has been inspected according to legal national and international requirements (AVV-HFP, EASA 965/2012, ICAO Annex 14 Vol. II and ICAO Heliport Manual) and, where applicable, to other national standards for offshore helidecks (CAP 437). The helideck has been found suitable for helicopter operations subject to below stated limitations, non-compliances and authorization by the approving authority. For more details see respective *Helideck Information Chart*.

HELIDECK INFORMATION

D VALUE	POSITION	MTOW
22.20 m	VARIABLE	9.5 t
LIMITATIONS		
NO HELICOPTER LANDINGS WHILE AFLOAT		
NON-COMPLIANCES		
OBSTACLE-FREE SECTOR INFRINGED BY HANDRAILS NEXT DUE		
21.10.2021		
Steffen Bechte/		

22.10.2020

Inspection date

BDSF-geprüfter Sachverständiger für Offshore Flugbetrieb, Hubschrauberlandedecks und Windenbetriebsflächen und Windenbetriebsflächen BDSF 8260120 RUNG FLUSCHER SACHVERSTÄNDIGER UND FLUSCHER SACHVERSTÄNDIGER UND FLUSCHER

1.01

Inspected by