

HELIDECK INSPECTION

CERTIFICATE

SEAFOX2

SEAFOX

The above-mentioned helideck has been inspected according to legal national and international requirements (AVV-HFP, EASA 965/2012, ICAO Annex 14 Vol. II and ICAO Heliport Manual) and, where applicable, to other national standards for offshore helidecks (CAP 437). The helideck has been found suitable for helicopter operations subject to below stated limitations, non-compliances and authorization by the approving authority. For more details see respective *Helideck Information Chart*.

HELIDECK INFORMATION

D VALUE	POSITION	MTOW
22.20 m	VARIABLE	9.5 t
/		
	LIMITATIONS	
	NO HELICOPTER LANDINGS WHILE AFLOAT	
	NON-COMPLIANCES	
OBST	ACLE-FREE SECTOR INFRINGED BY HANDR	AILS
	.:/	
	NEXT DUE	
	Special	
09.02.2023		
	Steffen Bechtel	1.01
09.02.2022		1.11/
Inspection date	BDSF-geprüfter Sachverständiger für Offshore Flugbetrieb, Hubschraubertandedecks und Windenbetriebsflächen	Inspected by
	BOSE SPORTS	

HER SACHVERSTÄNDIGER UN