

HELICOPTER HOIST AREA INSPECTION CERTIFICATE

SENVION 6.2M 126

OWF NORDERGRÜNDE

The helicopter hoist areas on stated wind turbine generators and located in mentioned offshore wind farm have been inspected according to legal national regulations (SOLF) and, where applicable, to other national standards for offshore helidecks. The hoist areas have been found suitable for helicopter hoist operations subject to below stated limitations, non-compliances and authorization by the approving authority.

