

## HELIDECK INSPECTION

## **CERTIFICATE**

## WIND OF CHANGE

Louis Dreyfus Armateurs S.A.S.

The above-mentioned helideck has been inspected according to legal national and international requirements (AVV-HFP, EASA 965/2012, ICAO Annex 14 Vol. II and ICAO Heliport Manual) and, where applicable, to other national standards for offshore helidecks (CAP 437). The helideck has been found suitable for helicopter operations subject to below stated limitations, non-compliances and authorization by the approving authority. For more details see respective *Helideck Information Chart*.

## HELIDECK INFORMATION

D VALUE	POSITION	MTOW
17.60 m	VARIABLE	7.0 t
/.<	LIMITATIONS	
3	NIL	2
	NON-COMPLIANCES	
OBSTACLE-FREE SECTOR INFRINGED BY HANDRAILS		
FOR FURTHER DETAILS SEE HELIDECK INFORMATION CHART		
SOPCIE		
NEXT DUE		
28.08.2020		
Jan-Henrik Barkow		
28.08.2019	RAS	120
Inspection date	BDSF-Geprüfter Sachverständiger für Offshore Flugbetrieb, Hubschrauberlandedecks & Windenbetriebsflächen	Inspected by